

Cingular/AT&T Treo 680 & 700p FIX for wireless Innovia Issues

Go to the web/browser and go to options by clicking the Blazer bar at top of screen, then click "options."

From the options page click on "preferences."

From the preferences page click on the advanced tab.

From the advanced page click on "set proxy" button at the bottom right.

From the Set Proxy page uncheck "carrier proxy."

Leave all proxy's blank/unset and unchecked.

Click "OK."

Clear cache & cookies on the way out on the advanced page.

OPTIONAL: reset/reboot device by removing battery*.

*must have at least 50% battery level on device

www.daytonarealtors.com/mobile to use our mobile site which has links for wireless InnoVia as well as other sites useful for our members.